




传感器
CN1619



外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab 长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm) 400	(mm) 192	(mm) 128	(mm) 0.2	(mm) 162	(mm) 192	(mm) 3.5	(mm) 5.5	30	(mm) 3.9	(mm) 6.5	30	900	(感测点/cm ²) 2.8
(in) 15.75	(in) 7.56	(in) 5.04	(in) 0.008	(in) 6.38	(in) 7.56	(in) 0.138	(in) 0.217	30	(in) 0.154	(in) 0.256	30	900	(感测点/in ²) 18

量程

kPa	3,448
psi	500