




传感器  
**CN3211**



外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab 长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量 (感测点/cm <sup>2</sup> )
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm) 402	(mm) 356	(mm) 202	(mm) 0.35	(mm) 326	(mm) 116	(mm) 4.9	(mm) 6.3	52	(mm) 1.5	(mm) 2.7	44	2288	(感测点/cm <sup>2</sup> ) 5.9
(in) 15.83	(in) 14.02	(in) 7.95	(in) 0.013	(in) 12.83	(in) 4.57	(in) 0.192	(in) 0.248	52	(in) 0.059	(in) 0.106	44	2288	(感测点/in <sup>2</sup> ) 38

量程

kPa	3,448
psi	500