




传感器
CN3811



外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab 长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列		行			感测点总数量	单位面积感测点数量	
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>			数量 <i>Qty.</i>
(mm) 420	(mm) 399	(mm) 300	(mm) 0.2	(mm) 389	(mm) 110	(mm) 5	(mm) 7.5	52	(mm) 4.5	(mm) 7	16	832	(感测点/cm ²) 1.9
(in) 16.54	(in) 15.7	(in) 11.81	(in) 0.008	(in) 15.3	(in) 4.33	(in) 0.197	(in) 0.295	52	(in) 0.177	(in) 0.276	16	832	(感测点/in ²) 12.3

量程

kPa	3447
psi	500